# **STERLING**

## **Metal Cross-Linked Polymer Finish**

New versatile crystal clear finish allows the beauty of the floor to shine through without yellowing. This metal interlock floor finish protects your floor and creates a burnishable finish with high shine and long life. Outstanding performance in low and high-speed maintenance programs. Self-leveling and self-sealing product. For use on all resilient flooring including most stone substrates. Designed for moderate ultra high speed maintenance programs, 3-4 times per week.



#### PRODUCT INFORMATION:

- Crystal clear finish allows the beauty of the floor to shine through
- Our most versatile, easy to apply and maintain floor finish
- · Outstanding performance in multiple maintenance programs

рН	8.0 - 9.0
Form	Liquid
Fragrance	Acrylic
Color	White
Packaged	4/1 gl Case, 5 gl Pail, 55 gl Drum

### **DIRECTIONS FOR USE:**

**INITIAL APPLICATION:** Completely strip all old wax or finish with Animal™. Be careful to follow the "Directions for Use" for the selected stripper. Remove the stripping solution with wet vac or autoscrubber. Detail mop to remove all remaining residue and allow floor to completely dry. Repeat if necessary. Floor must be clean, dry and free of all residue. Apply 1 or 2 even coats of Foundation™ sealer (optional, based on condition of floor), and let dry. Apply finish in uniform, thin coats. Allow each coat to dry for 20 to 30 minutes, or until surface is completely dry to the touch, before applying additional coats. Allow an extra 10 minutes drying time for each additional coat. Total of 4-6 coats of finish are recommended.

**ROUTINE MAINTENANCE:** Sweep large debris and remove. Dust mop to remove dry soil, then damp mop or automatic scrub with Rinse No More™ cleaner. Buff or burnish the floor as desired. Use of our Reflex™ is recommended to extend time between top scrub and recoating.

INTERIM MAINTENANCE: Sweep large debris and remove. Dust mop to remove dry soil, then damp mop or automatic scrub with Rinse No More™. Top scrub with Lacto ™ and recommended floor pad to remove top soiled layers of finish. Floor must be clean, dry and free of all residue. Apply 1-2 coats of finish as directed under "Initial Application" on this label.

#### **KEEP FROM FREEZING**

Slip resistance meets or exceeds ASTM D 2047-04 James Machine 0.5 minimum.

### **IMPORTANT SAFETY INFORMATION:**



#### WARNING

Suspected of damaging fertility or the unborn child.

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood.

PRECAUTIONARY STATEMENTS: Wear protective gloves, protective clothing, eye protection and face protection.

Dispose of contents and container in accordance with local, regional, national and international regulations.

FIRST AID: If exposed or concerned: Get medical attention.

Emergency Response Number ChemTel Inc. 1-800-255-3924



DI DIM