

HOW TO RECOAT A FLOOR

Tools & Materials Needed:

- Bucket with wringer
- Liner
- Finish mop
- "Wet floor" signs Gloves and goggles

Procedures:

Purpose of Recoating the Floor

• Bring gloss level back.

Restore finish layer worn away through:

Foot traffic

Top scrubbing

Procedure for Recoating a Floor

- Put "Wet floor" signs at all entrances.
- Start with a top scrubbed floor. Allow floor to dry.
- Put on gloves and goggles.
- Pour finish into liner in mop bucket.
- Dip finish mop into floor finish. Wring out just to point that it is not dripping.
- Start at furthest corner from door.
- Frame a small area and fill in using a figure eight pattern.
- Turn mop frequently.
- Apply finish all the way to the baseboard.
- Work backwards toward the door.
- Continue working side by side areas, keeping overlapping edges wet.
- Allow finish to dry thoroughly.
- Clean up.

Wash out finish mop, hang to dry.

Throw away leftover finish and liner. Twist, tie and toss.

Clean all equipment and store for future use.





